Seat	
No.	

[5668]-114

S.E. (Mechanical/Automobile) (First Semester) EXAMINATION, 2019 MATERIAL SCIENCE

(2015 PATTERN)

Time: Two Hours

Maximum Marks : 50

- N.B. :— (i) Solve Q. No. 1 or Q. No. 2, Q. No. 3 or Q. No. 4, Q. No. 5 or Q. No. 6, Q. No. 7 or Q. No. 8.
 - (ii) Figures to the right indicate full marks.
 - (iii) Draw the neat sketch wherever necessary.
- 1. (a) Draw Lattice planes for the following Miller indices: [4]
 - $(1) \qquad (2 \quad 2 \quad 1)$
 - $(2) \qquad \qquad 1 \qquad 0)$
 - (b) Differentiate between BCC and FCC structure on the basis of the following: [4]
 - (1) Atomic packing factor
 - (2) Average no. of atoms per unit cell
 - (3) Relation between radius of atom and lattice parameter.
 - (4) Example of Material
 - (C) What do you mean by the term "imperfections in crystal structure? [4]

P.T.O.

Differentiate between slip and twinning on the basis of the
following parameters : [4]
(1) sketch
(2) definition
(3) required stress to produce slip/twinning
(4) direction of the slip/twinning
Discuss the Dislocation theory of work hardening with neat
sketch. [4]
Define "volume density" of a metal. Calculate the X ray density
of aluminum. Given: Lattice constant: 4.049A°, atomic weight
26.98 gm/mole and Avogadro's number = 6.02×10^{23}
atoms/mole. [4]
Identify the type of mechanical testing for the following
(any five): [5]
(i) Determination of strength, resilience, toughness etc. of
material.
(ii) Susceptibility of materials for brittle failures under the
existence of stress, temperature, strain rate etc.
(iii) Failure of material at a stress level far below its ultimate
tensile strength when acted upon by frequent stress
fluctuations.
(iv) The slow and progressive deformation of a material with
time under a constant stress and high temperature.
2

	(V) Material inspection for detecting internal defects such as
	cracks, porosity and laminations in metallic and
	non-metallic components during or after production.
	(vi) Inspection of many components at the same time.
(b)	Explain "Ultrasonic inspection method" with neat sketch,
	advantages and disadvantages. [4]
(C)	Explain any four corrosion prevention and control methods.
	[4]
	Or
4. (a)	Explain the reason for the following types of corrosion
	(any five): [5]
	(1) Pitting corrosion
	(2) Stress Corrosion
	(3) Capitation corrosion
	(4) Untergranular corrosion
	(5) Crevice corrosion
	(6) Galvanic corrosion
	(7) Caustic embrittlement
(b)	What do you mean by the term "Fatigue in material" ? List
	out various methods to increasing the fatigue life? [4]
(C)	What are the various points should be considered before selecting
	the materials for a particular service environment. [4]
[5668]-114	3 P.T.O.

5.	(a)	Explain with neat sketch, advantages and disadvantages the
		Ion Implantation method of surface modification. [5]
	(b)	Describe the following terms with neat sketches (any two):
		(1) Shot Blasting
		(2) Plasma nitriding
		(3) Anodizing [4]
	(C)	Explain with neat sketch the process of electroplating? List
		out the various factors which affect the electroplating. [4]
		Or
6. (a) (b)	(a)	Explain with neat sketch, advantages and disadvantages the
		Ion vapor deposition method of surface modification. [5]
	(b)	Draw self-explanatory figure of Physical vapor deposition and
	chemical vapor deposition of method of surface modification.	
		addition [4]
	(c)	List on any four coatings defects with its probable causes.
		[4]
		CXV
7.	(a)	Define the term 'powder metallurgy' with basic steps and
		applications. [4]
	(b)	Explain any twopowder manufacturing processes for the following
		types : [4]
		(1) Mechanical processes.
	(2) Chemical processes.	
[5668	1-114	$\it \Delta$

	(C)	Explain the role of powder metallurgy for manufacturing	of
		'cemented carbide' with neat flow chart ?	[4]
		Or	
8.	(a)	Explain the types of methods for measurement of powder size	
		and distribution in powder metallurgy.	[4]
	(b)	What are the various compacting or pressing properties	of
		powder in powder metallurgy ?	[4]
	(c)	What is a 'self-lubricated bearing'? Explain the role of powder	
		metallurgy for manufacturing of 'self-lubricated bearings'	?
		download from Silvida.	[4]
		Stule	