GUJARAT TECHNOLOGICAL UNIVERSITY

B. E. - SEMESTER - VI • EXAMINATION - WINTER 2012

| Subject code: 161907 Dat | | code: 161907 Date: 09/01/2 | e: 09/01/2013 | |
|--------------------------------------|------------|---|---------------|--|
| Subject Name: Industrial Engineering | | | | |
| Time: 02.30 pm - 05.00 pm Total Mar | | | : 70 | |
| | | ions: | | |
| | | Attempt any five questions. | | |
| | 2. | Make suitable assumptions wherever necessary. | | |
| | 3. | Figures to the right indicate full marks. | | |
| Q.1 | (a) | Differentiate between product layout and process layout by taking | 07 | |
| • | . , | suitable example | | |
| | (b) | Explain in detail method of weighted moving average | 07 | |
| Q.2 | (a) | Explain in brief operation process charts and machine data cards | 07 | |
| | (b) | Explain Economic order quantity | 07 | |
| | | OR | | |
| | (b) | Discuss in detail assembly line balancing. | 07 | |
| | | | | |
| Q.3 | (a) | 1 11 , | 07 | |
| | (b) | | 07 | |
| 0.1 | () | OR | 05 | |
| Q.3 | (a) | | 07 | |
| | (b) | Describe the quality circles. | 07 | |
| Q.4 | (a) | State the importance of micro motion study | 07 | |
| ۳.۷ | (a) (b) | | 07 | |
| | (6) | OR | 07 | |
| Q.4 | (a) | Explain in brief various charts and diagrammes utilized in method | 07 | |
| ~ ·· | (44) | study. | 0. | |
| | (b) | | 07 | |
| | | | | |
| Q.5 | (a) | What are factory act? What are major provisions for safety and health? | 07 | |
| | (b) | Define wages and explain in detail various types of incentives. | 07 | |
| | | OR | | |
| Q.5 | (a) | · · · · · · · · · · · · · · · · · · · | 07 | |
| | (b) | State various sources of industrial finance and government incentives to entrepreneurs. | 07 | |
